



BEHR PREMIUM® DECKOVER™ Cleaner

No. 5009 Cleaner

- Cleans and Brightens Areas Coated with DECKOVER®
- Easily Removes Dirt, Household and Mildew Stains
- Ready to Use, No Mixing Required
- Covers Up To 200 Sq. Ft. Per Gallon



Coverage:
Full Strength 200 Sq. Ft.



Keep Surface Wet
During Use



Clean-Up:
Soap & Water

IMPORTANT! Do not open product without reading these instructions.

WHERE TO USE

Use as a maintenance cleaner on Exterior surfaces coated with the DECKOVER® coating including Decks, Fences, Siding, Patios, Walkways, Porches and Boat Docks. Extremely effective on dirt and against greasy, oily stains such as barbecue grease. Ideal for use on grime and most fluid stains. **DO NOT USE ON:** Uncoated wood surfaces, or non-DECKOVER coated surfaces.

CAUTION: Surfaces may become slippery when wet. Use caution when walking on surface when moisture is present.

PREPARATION †

(The following steps are required.) Wipe up any excess oil and grease. Sweep away dirt and loose contaminants. Test Patch: Test product on an inconspicuous area to ensure product performance. Protect grass and any nearby plants by dampening these areas with water and covering with plastic drop cloths. Prevent all rinse solution from entering storm drains. Product is ready to use and does not require dilution.

APPLICATION

Use goggles during application. Wear acid resistant clothing, boots and gloves. Actual coverage will depend on method of application and cleaning technique. Apply BEHR PREMIUM DECKOVER Cleaner No. 5009 directly on dry, stained areas and work into surface with stiff bristled, non-metal brush or broom. For best results, use a plastic watering can or plastic pump sprayer to evenly distribute product. Let stand 10-20 minutes then scrub vigorously. Do not allow product to dry on the surface. NOTE: Heavily stained areas or older stains may require additional application. After application, thoroughly saturate surrounding grass and plants with fresh water. Rinse surface thoroughly with fresh water while scrubbing to properly remove all remaining residue. Rinse using garden hose. Remove excess water with a non-metal squeegee or mop.

LIMITED WARRANTY

Behr Process Corporation warrants that this product meets Behr's manufacturing specifications. If this product does not meet these specifications, Behr Process Corporation will, at its option and upon proof of purchase, either furnish an equivalent amount of new product to you or refund the purchase price of this product. **This guarantee excludes (1) labor and costs of labor for application or removal of any product; or (2) any incidental or consequential damages, whether based on breach of express or implied warranty, negligence, strict liability or any other legal theory.** Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. This warranty gives you specific legal rights and you may also have other rights, which vary from state to state.

To consult with a Behr Certified Coatings Professional, call 1-800-854-0133 Ext. 2 (U.S.A. only).

DISPOSAL

Thoroughly rinse all surfaces, clothing and tools with fresh water after use. In case of contact with non-DECKOVER painted or finished surfaces, rinse immediately with fresh water. Properly dispose of soiled rags. To recycle or properly dispose of product in your community, contact your household refuse collection service.

† WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

DANGER! CORROSIVE! WILL CAUSE EYE BURNS AND PERMANENT TISSUE DAMAGE. HARMFUL IF SWALLOWED. CONTAINS POTASSIUM HYDROXIDE. AVOID CONTACT WITH SKIN. MAY CAUSE PERMANENT SKIN DAMAGE AND SEVERE RESPIRATORY SYSTEM IRRITATION. USE WITH ADEQUATE VENTILATION. Use goggles during application. Wear acid resistant clothing, boots and gloves. Avoid breathing spray mist. If properly used, a respirator may offer additional protection. **FIRST AID:** Eye and skin contact: In case of eye or skin contact, flush immediately with water for 20 minutes. Get medical attention if irritation or symptoms of overexposure persist. If inhaled, move to fresh air. If swallowed, DO NOT induce vomiting. Get medical attention immediately. Give water to dilute material in stomach. Never give anything by mouth to an unconscious person.

CAUTION: KEEP OUT OF REACH OF CHILDREN-DO NOT TAKE INTERNALLY.

BEHR
A Masco Company

©2014 Behr Process Corporation
Santa Ana, CA 92704 U.S.A. • behr.com
V.O.C. (G.O.V.) <0.5 WT. % • REV. 6/14