



BEHR PREMIUM® Granite Grip™

- Revives Concrete Surfaces
- Durable, Protective Finish
- Available in Custom Colours
- Fills in Hairline Cracks
- Resists Dirt, Grease & Household Stains

No. 650 Gray

No. 655 Tan



Spread Rate:
Rough 4-5 m² (40-50 sq. ft.)
Smooth 5-6 m² (50-60 sq. ft.)



**2 Coats
Required**



Dry Time:
1 Hr. Dry to Touch
3-4 Hrs. Recoat



**Protect
from Freezing**

**IMPORTANT! DO NOT OPEN CONTAINER WITHOUT READING INSTRUCTIONS.
2 COATS REQUIRED. USE WITH 3 mm ADHESIVE ROLLER COVER.**

WHERE TO USE

On Interior/Exterior surfaces such as: Porous Concrete, Masonry, Stone and Brick. Ideal for horizontal surfaces such as: Walkways, Patios, Porches and Pool Decks.

WHERE NOT TO USE

DO NOT use on vertical surfaces or areas subject to hydrostatic pressure. NOT for industrial use or areas subject to forklifts. Do not use on drivable surfaces such as garage floors and driveways. Surfaces may become slippery when wet. Use caution when walking on surface when moisture is present.

PREPARATION*

(Proper surface preparation is required.) All surfaces must be clean, sound, dry and free of any dirt, oil and grease. Uncoated Concrete or Masonry Surfaces: Allow new surfaces to cure 30 days. Clean and etch surface using a product such as BEHR PREMIUM No. 991 Concrete & Masonry Cleaner & Etcher to achieve a textured profile similar to 150 grit sandpaper. Painted Surfaces-Concrete: For a painted surface in sound condition, use a product such as BEHR PREMIUM No. 990 Concrete & Masonry Degreaser & Cleaner to clean and prepare the surface. If the coating is failing or peeling, use a paint stripper such as BEHR PREMIUM No. 992 Concrete & Masonry Paint Stripper to remove old coating or scrape/sand down to a sound concrete surface. Scuff sand glossy surfaces. Clean and spot etch any exposed concrete using a product such as a BEHR PREMIUM No. 991 Concrete & Masonry Cleaner & Etcher. Remove all dust with a damp cloth, allow to dry.

APPLICATION

DO NOT THIN. Intermix all cans of same product to ensure colour uniformity. Stir before applying. Use product when air and surface temperatures are between 10-32° C. Do not apply in direct sunlight. For hairline cracks up to 0.3 cm, completely fill in with coating using a nylon/polyester brush and allow

to dry completely prior to roller application. Do not pour product directly on surface; always use a roller tray. Apply a first coat using a 3 mm roller cover for adhesives, nylon/polyester brush or synthetic stain pad. NOTE: The first coat will act as the base coat and it will not completely cover the surface by design. Avoid over application on the first coat. Apply in 1.2 m x 1.2 m sections. Begin with the roller in the center of the section and roll outwards in random directions. Avoid regular patterns and knock down hard edges using the roller. Allow first coat to dry then apply second coat in the same method as the first coat. While two coats are necessary, additional coats may help hide previous surface imperfections or cover over dark colours. For large projects, consider using a texture sprayer with a 4 mm tip. Spray in 1.2 m x 1.2 m sections and back roll with an adhesive roller cover. Soap & water clean-up.

DRY TIME

Longer dry time required in cooler temperatures and in higher humidity. The floor may be subjected to light foot traffic after 24 hours. Allow 72 hours before subjecting surface to heavy foot traffic or repositioning furniture. Premature heavy traffic will cause paint failure requiring spot recoating.

CLEAN UP

Wait at least 30 days before rinsing or cleaning. Use a mild detergent as needed. Abrasive cleaners and pressure-washers should be used carefully to avoid premature coating failure. DISPOSAL Properly dispose of all soiled rags. To recycle or properly dispose of product in your community, contact your household refuse collection service

† WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Center at 1-800-424-LEAD or log on to www.epa.gov/lead.

LIMITED WARRANTY If this product is found to be defective upon inspection by an expert, Behr Process Corporation will, at its option, and upon presentation of proof-of-purchase (the original receipt), either furnish an equivalent amount of new product or refund the original purchase price of this product to you. This warranty is not transferable. If you believe this product is defective, contact Behr Process Corporation at 2750 Centre Avenue N.E., Calgary, AB T2A2L3. The cost of transportation or shipping, if any, are to be assumed by the consumer. The clause of limitation of liability which follows is inapplicable in Quebec: **This warranty excludes (1) labour and costs of labour for the application or removal of any product, and (2) any incidental or consequential damages, whether based on breach of express or implied warranty, negligence, strict liability or any other legal theory.** The above provisions are not intended to operate where prohibited by law. This limited warranty is the only warranty provided by Behr Process Corporation unless extended by a provincial consumer statute.

To consult with a BEHR Certified Coatings Professional, call 1-800-661-1591.

CAUTION! IRRITANT! HARMFUL IF SWALLOWED. MAY CAUSE EYE, NOSE AND THROAT IRRITATION. AVOID CONTACT WITH SKIN AND EYES AND AVOID BREATHING OF VAPORS AND SPRAY MIST. WEAR EYE PROTECTION AND PROTECTIVE CLOTHING. USE ONLY WITH ADEQUATE VENTILATION. To avoid breathing vapors and spray mist, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches or dizziness, increase fresh air. If properly used, a respirator (NIOSH approved for organic vapor with P series particulate pre-filter) may offer additional protection; obtain professional advice before using. A dust mask does not provide protection against vapors. Avoid contact with eyes and skin. Wash thoroughly after handling. Close container after each use. **FIRST AID:** If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention; for skin, wash thoroughly with soap and water. If swallowed, get medical attention immediately.

CAUTION: KEEP OUT OF REACH OF CHILDREN – DO NOT TAKE INTERNALLY.

BEHR
A Masco Company

©2016 Behr Process Corporation
Santa Ana, CA 92704 U.S.A. • behr.com
V.O.C. (C.O.V.) <50 g/L • REV. 5/16