

BEHR PREMIUM™ AEROSOL

- Interior/Exterior
- Drip & Run Resistant
- Excellent Adhesion

B000144C B000244C B000344C B000544C B000544C B000644C B000844C B000844C B001044C B001144C B001244C B001544C B001744C B001744C	Black Orion Gray Lunar Surface Hidden Sea Glass Inked Blazing Bonfire Baronial Brown No More Drama Flirt Alert Unmellow Yellow Luck of the Irish Congo Tropics Mayan Treasure Outdoor Café Khaki Shade	B005244C B005544C B005644C B005744C B005944C B006244C B007644C B007644C B008644C SATIN B003044C B004444C B006444C B006644C	Independence Blue Electric Grape Tree Top Green Roasted Corn Kindling Rusty Gate Adored Blue Toasty Gray Ocean Abyss King's Court Graphic Charcoal Fiji Amazon Moss Ashen Tan Top Tomato Black	B007244C B0087744C B008044C B008844C FLAT B002044C B002144C B006144C B007844C B007944C B008344C SEMI-GLOS B005044C PRIMER B004744C B004944C	Off-White White Primer	
B001844C B001944C B003944C	Khaki Shade White Sweetheart	B006844C B006944C B007044C		B004944C	Gray Primer	



Protect from Freezing



15-30 minutes
Dry to Touch
<1 Hr or greater
than 24 Recoat time



1-2 m² (10-20 sq ft) Coverage



Mineral Spirits Clean-Up

BEHR PREMIUM™ Aerosol features an enhanced formulation that combines paint and primer† in a single can, delivering a premium, durable finish. Designed for both indoor and outdoor uses. BEHR PREMIUM™ Aerosol can be used on wood, metal, cast stone, and wicker. Weather and corrosion resistant, it delivers a reliable, long-lasting finish. The unique, ergonomic shape of the BEHR PREMIUM™ Aerosol can and its comfortable tip deliver a superior spray experience that fights fatigue so you can create a smooth finish every time.

[†]A Primer coat may be needed on some surfaces.

PREPARATION

- The surface must be clean, free of dust, grease, wax, peeling paint, mold, and mildew. If washing is necessary, use a non-soapy detergent or a TSP substitute. Rinse well and allow to dry.
- Peeling or Checked Paint: Scrape off loose paint and sand to a smooth surface. Sanding or removal of paint containing lead is hazardous
- *Glossy Surfaces: For maximum adhesion, scuff sand the surface thoroughly before painting.

APPLICATION

- Eye protection is recommended.
- For best results, use at room temperature. Cover adjacent areas to protect from overspray.
- Shake can vigorously for one minute after mixing ball begins to rattle and
 often during use. Hold can upright, moving from side-to-side while spraying
 lightly and evenly about 20 30 cm (8" 12") from area being painted. Two
 to three thin coats produce best results.
- USE BEHR® Primer for enhanced adhesion over bare wood.
- . Apply thin coats to avoid runs and sags.

*LIMITED WARRANTY For one year from the date of purchase, Behr Process Corporation warrants to the original consumer purchaser, (1) that the product meets Behr's manufacturing specifications, and (2) the performance of this product when applied according to the label instructions and specifications. If this product is found not to perform as specified on the label within one year from the date of purchase, Behr Process Corporation will, at its option and upon presentation of proof-of-purchase (the original receipt), either furnish an equivalent amount of new product or refund the original purchase price of this product to you. This warranty excludes (1) labour and costs of labour for the application or removal of any product, and (2) any incidental or consequential damages, whether based on breach of express or implied warranty, negligence, strict liability or any other legal theory. Some provinces do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. To the extent permitted by applicable law, any implied warranties including the implied warranties of merchantability and of fitness for a particular purpose, are limited to the duration of this express warranty. Some provinces do not allow limitations on how long an implied warranty lasts, so the above limitation may not apply to you. This warranty gives you specific legal rights and you may also have other rights, which vary from province to province. To obtain warranty service, call 1-800-661-1591. Behr Process Corporation reserves the right to inspect any and all application of the product prior to processing your claim made under this warranty.

To consult with a Behr Paint Company representative, call 1-800-661-1591.

BEHR

DRY TIME

- Dry Time: @ 25°C (77°F) and 50% RH: To Touch: 15 – 30 minutes
- . To Recoat: before 1 hour or after 24 hours
- Dry times are temperature, humidity, and film thickness dependent.

CLEAN-UP & DISPOSAL

- Clear spray valve immediately after use by turning can upside down and spraying until only clear gas is released. If spray nozzle becomes clogged, remove and clean.
- . Do not stick pins or wire into can opening.
- Clean fresh overspray with mineral spirits or paint thinner. Remove dried paint with paint remover, but test small area first to ensure paint remover does not damage substrate.
- Please consider donating any unused product. For recycling or disposal information contact your local household refuse collection service.

Visit behr.ca for painting tips, project advice and colour coordination with the ColourSmart by BEHR™ Tool, or download the ColourSmart by BEHR App on vour mobile device.

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. Contact Health Canada at 1-866-225-0709 or log on to www. canada.ca/en/health-canada/services/home-safety/lead-based-paint.

EXTREME DANGER! VERY FLAMMABLE, POISON, IRRITANT, CONTENTS UNDER PRESSURE. CONTENTS MAY CATCH FIRE. CONTENTS HARMFUL. FUMES HARMFUL MAY IRRITATE EYES AND SKIN. CONTAINER MAY EXPLODE WHEN HEATED. DO not smoke. Do not swallow. Avoid contact with eyes, skin and clothing. Do not breathe fumes. Do not puncture. Do not burn. Use only with adequate ventilation. Wear a mask/respirator while handling the product. Keep away from flames, such as pilot light, and any object that sparks, such as an electric motor. Keep out of reach of children. Wear eye protection and protective clothing. Store away from heat. FIRST AID TREATMENT: May contain: ACETONE; BUTYL ACETATE; PROPANE; TITANIUM DIOXIDE; ISOBUTANE; GROUND CALCIUM CARBONATE; 1-METHOXY-2-PROPYL ACETATE: METHYL ETHYL KETONE: STODDARD SOLVENT: CARBON BLACK; IRON OXIDE; 3-ETHOXYPROPIONIC ACID ETHYL ESTER; SOLVENT NAPHTHA (PETROLEUM), LIGHT AROM.; DISTILLATES (PETROLEUM), HYDROTREATED LIGHT; TALC; LIMESTONE; NEPHELINE SYENITE; SILICON DIOXIDE; AND NAPHTHA (PETROLEUM), HYDROTREATED HEAVY. If swallowed, call Poison Control Centre or doctor immediately. Do not induce vomiting. If in eyes rinse with water for 15-20 minutes. If on skin rinse will with water. If inhaled move person to fresh air.